

Center Support Bearings

BCA is your complete aftermarket partner.

BCA center support bearings are engineered to be a direct replacement for worn OE components. Many SUVs and trucks, as well as some passenger vehicles, use a driveshaft center support bearing to connect and support two sections of driveshaft. Driveshafts are precision components that are carefully balanced before a vehicle leaves the factory and these center support bearings help to absorb and isolate harmonic vibrations as the driveshafts rotate. Under normal operating conditions, these components will develop wear and eventually require replacement.

As your complete automotive aftermarket partner, BCA's growing product line includes hundreds of the most popular applications for driveshaft center support bearings.

BCA Center Support Bearing Features:

- Pre-lubricated and sealed bearing inserts prevent grease leakage while keeping moisture and contaminants out.
- High-quality rubber absorbs and isolates vibrations to extend bearing life.
- Cold-rolled steel construction increases strength and durability while a corrosion-resistant coating protects from environmental elements.



BCABearings.com

© Copyright 2024, NTN Bearing Corporation of America. The BCA name is a registered trademark of NTN USA. The BCA Bearings logo and bearing icon are trademarks of NTN USA.

Popular BCA Driveshaft Center Support Bearing Applications*

| Part Number | Application |
|--------------------------|--|
| | 1280-1410 Series U-Joints |
| NBHB88107D | |
| NBHB88107C | 1280-1410 Series U-Joints 1310-1550 Series U-Joints |
| NBHB88508D | 1700-1710 Series U-Joints |
| NBHB88510S | |
| NBHB88512ASHD | 1760-1810 Series U-Joints |
| NBHB88512SA | 1760-1810 Series U-Joints, Self-Aligning |
| NBHB88561 | SPL70 Series U-Joints BMW 325i 01-06 |
| NBHB278020 | BMW 528i 97-00 530i 95 |
| NBHB278080 | BMW 5281 97-00 5301 95 BMW 530i 01-03 |
| NBHB35 NBHB34 | BMW 740i 93-98 |
| NBHB88560 | Cadillac Escalade 08-12 |
| NBHB88515 | Cadillac Escalade 99-07 |
| NBHB3074A | Cadillac Escalade 99-07 Cadillac STS 05-11 |
| NBHB88505 | Chevrolet Avalanche 07-13 |
| NBHB88505 NBHB108 | Chevrolet Blazer 87-94 |
| NBHB108 NBHB88520 | Chevrolet C3500 92-96 |
| NBHB88520 NBHB88508E | Chevrolet C3500 92-96 Chevrolet C50 80-90 |
| NBHB88509C | Chevrolet C5500 Kodiak 90-91 |
| | Chevrolet Colorado 04-12 |
| NBHB159510 | |
| NBHB88555 | Chevrolet Equinox 05-07 |
| NBHB88530 | Chevrolet S10 95-04 Chevrolet Silverado 1500 01-06 |
| NBHB88508A | |
| NBHB88532 | Chevrolet Silverado 1500 99-15 |
| NBHB88540 | Chevrolet Silverado 2500 99-04 |
| NBHB108D NBHB44 | Chevrolet Silverado 2500 HD 01-07 |
| NBHB88528 | Dodge Charger 06-13 Dodge Dakota 05-10 |
| NBHB88536 | Dodge Ram 2500 03-05 |
| NBHB4023A | Dodge Ram 2500 03-03 |
| NBHB4023A NBHB88547 | Dodge Ram 2500 06-09 |
| NBHB88108D | Dodge Ram 2500 94-02 |
| NBHB88508AB | Dodge Ram 2500 94-02 Dodge Ram 2500 94-02 |
| NBHB4037A | Dodge Ram 3500 1555 Series 2010 |
| NBHB4037A NBHB30 | Dodge Ram 50 87-93 |
| NBHB88554 | Dodge Sprinter 2500 03-06 |
| NBHBD206FF | Ford Aerostar 90-97 |
| NBHBB200FF | Ford E-250 08-14 |
| NBHB88526 NBHB88508AA | Ford F Super Duty 93-97 |
| NBHB88508AA NBHB88514 | Ford F-150 97-03 |
| NBHB88518 | Ford F-150 97-03 Ford F-250 Super Duty 04-15 |
| NBHB88518 NBHB88525 | Ford F-250 Super Duty 04-15 Ford F-250 Super Duty 07-12 |
| NBHB88525 NBHB88527 | Ford F-250 Super Duty 07-12 Ford F-250 Super Duty 08-10 |
| NBHB88508F | Ford F-250 Super Duty 99-04 |
| NBHB88508G | Ford F-250 Super Duty 99-04 Ford F-250 Super Duty 99-04 |
| NBHB885086 | Ford F-250 Super Duty 99-04 |
| NBHB88523 | Ford F-350 Super Duty 08-10 |
| NBHB88551 | Ford F-350 Super Duty 08-10 |
| NBHB88552 | Ford F-350 Super Duty 08-10 |
| NBHB88529 | Ford F-350 Super Duty 08-13 |
| NBHB88550 | Ford F-350 Super Duty 08-13 |
| NBHB88549 | Ford F-350 Super Duty 08-13 |
| NBHB88553 | Ford F-350 Super Duty 11-13 |
| NBHB88557 | Ford F-350 Super Duty 11-15 |
| NDF100033/ | Toru F-500 Super Duty 11-15 |

| Part Number | Application |
|--------------|----------------------------------|
| NBHB88508 | Ford F-450 Super Duty 1999 |
| NBHB88512A | Ford F-450 Super Duty 99-00 |
| NBHB88108FD | Ford F-550 Super Duty 99-07 |
| NBHB106FF | Ford Ranger 85-89 |
| NBHB88558 | Freightliner Sprinter 2500 07-10 |
| NBHB88509B | GMC C50-C7000 P4500 79-90 |
| NBHB88509 | GMC B6000 80-91 |
| NBHB88512AHD | GMC B7 93-97 |
| NBHB88508B | GMC C5000 80-90 |
| NBHB88510 | GMC C5000 Topkick 90-91 |
| NBHB88509A | GMC C6000 80-90 |
| NBHB206FF | GMC Jimmy 72-91 |
| NBHB88508C | GMC P4500 80-90 |
| NBHB88107E | GMC Sierra 1500 HD 05-06 |
| NBHB20 | Isuzu Pickup 81-87 |
| NBHB21 | Isuzu Pickup 81-87 |
| NBHB36 | Isuzu Pickup 88-95 |
| NBHB46 | Isuzu Pickup 88-95 |
| NBHB32 | Isuzu Rodeo 91-97 |
| NBHB33 | Isuzu Rodeo 91-97 |
| NBHB88107A | Isuzu Trooper 96-00 |
| NBHB1000 | Kia Sorento 03-04 |
| NBHB1001 | Kia Sorento 04-06 |
| NBHB1002 | Kia Sorento 05-06 |
| NBHB45 | Lexus IS300 04-05 |
| NBHB43 | Lexus LS400 95-00 |
| NBHB39 | Lexus LS400 93-94 |
| NBHB29 | Mazda B2200 82-93 |
| NBHB202510 | Mazda Tribute 01-06 |
| NBHB14 | Mitsubishi Mighty Max 83-91 |
| NBHB19 | Nissan 200SX 77-83 |
| NBHB18 | Nissan 620 75-79 |
| NBHB12 | Nissan 720 80-86 |
| NBHB13 | Nissan D21 86-94 |
| NBHB1009 | Nissan Frontier 98-04 |
| NBHB6 | Nissan Xterra 00-04 |
| NBHB41 | Pontiac Firebird 93-02 |
| NBHB88555UJ | Saturn Vue 02-07 |
| NBHB24 | Toyota 4Runner 89-95 |
| NBHB27 | Toyota 4Runner 90-95 |
| NBHB9 | Toyota 4Runner 90-95 |
| NBHB7 | Toyota Celica 82-86 |
| NBHB11 | Toyota Corolla 71-83 |
| NBHB1820-10 | Toyota Highlander 01-17 |
| NBHB1850-10 | Toyota Highlander 01-17 |
| NBHB16 | Toyota Pickup 69-77 |
| NBHB10 | Toyota Pickup 84-88 |
| NBHB17 | Toyota Pickup 84-88 |
| NBHB37 | Toyota RAV4 96-00 |
| NBHB38 | Toyota Supra 95-98 |
| NBHB28 | Toyota T100 93-98 |
| NBHB31 | Toyota Tacoma 95-04 |
| NBHB26 | Toyota Tundra 00-06 |
| NBHB202010 | Toyota Tundra 00-17 |

* Visit BCABearings.com for the most complete and up-to-date application data